

Buoy Committee Status Report September 2018

Buoy Number	Buoy Location	Status/Comments
1	Newton Bay – channel near boat launch: small buoy 19”	Good condition. Buoy is faded and could be replaced. Buoy removed, anchor left on rock with a plastic bottle. Responsible member: Claudio Micamonaco
2	Newton bay – Whalesback rock: small buoy 19”	Good condition. The first anchor fell below the water line, so a new anchor was put in place. Buoy removed, anchor left on rock with a plastic bottle. Need to try to recover the other anchor. Responsible member: Fraser Blackwell
3	McElaney’s rock (Gull rock): large buoy 23”	Good condition. This buoy came loose again. New cable was put on the anchor. Buoy removed, anchor left on rock with a plastic bottle. Stored at Robinsons
4	McElvaney’s rock (Gull rock) : small buoy 19”	Good condition. Recommended that we put a large buoy at this spot. Buoy removed, anchor left on rock with a plastic bottle. Stored at Robinsons
5	Manley’s rock: large buoy 23”	Good condition. Anchor and buoy removed. Buoy removed , anchor left on rock with with a plastic bottle. Stored at Robinsons
6	Mystery Island, north side: small buoy 19”	Good Condition. Anchor and buoy removed. Stored at Jean Duchesne cottage.
7.	Mystery Island, north side: small buoy 19	A new buoy was placed here to replace a bottle that was marking a second rock pile.
8.	Bowman sector: small buoy 19”	Good condition. Buoy removed and anchor marked with javex bottles. Stored at Gilles Proulx
9	Bowman sector: small buoy 19”	Good condition. Buoy removed and anchor marked with javex bottles. Stored at Gilles Proulx.
10	Spare Buoy – 19”	Stored at Robinsons

Buoy committee:

George Mellean

Margaret Robinson

Jean Duchesne

Gilles and Mark Proulx

Fraser Blackwell